ILLEGIB
Approved For Release 2001/07/31 : CIA-RDP78T05439A000500340034-6



Approved For Release 2001/07/31 : CIA-RDP78T05439A000500340034-6

~~CONFIDENTIAL~~ S 19621

CIA IMAGERY ANALYSIS DIVISION

NAME	COUNTRY	COORDINATES
Hung Nhan Highway Bridge Bridge No. 34 on NE 48-7	North Vietnam	18 04N - 106 18E XE 371981

REFERENCES

25X1D PHOTO [redacted]

MAP AMS L509 NE 48-7

BRIEF NO: PIB - 65030

LOCATION: 0.4 nm N.W. of Hung Nhan on Route 1

DESCRIPTION:

LENGTH [redacted] 25X1D

WIDTH

TYPE Deck 25X1D

MATERIAL Wood and Concrete

NO. OF SPANS 6

LENGTH OF EACH SPAN [redacted] 25X1D

STATUS: Three of the [redacted] spans are damaged, south approach of the bridge is damaged.

COMPENSATIVE ACTION: Possible placing of new beams on damaged spans

Declass Review by NIMA/DOD

~~CONFIDENTIAL~~

GROUP 1
Excluded from automatic downgrading and declassification